






Fort Calhoun: Licensee Event Reports (LERs) to the NRC

	Document Date	Document Title	Accession Number
	11/09/1999	LER 99-003-00, "Pressurizer Safety Valve Outside Lift Setting Acceptance Range."	ML993230052
	11/24/1999	LER 1999-005-00:on 10/29/99,failure to satisfy surveillance requirement for containment penetration,was discovered.Caused by inadequate corrective actions.Corrective actions:Physical check of all similarly configured penetrations conducted.	ML993350028
	11/24/1999	LER 99-004-00, "Loss of Both Station Vital Buses While Transferring Station Lighting." With 991124 Letter.	ML993350033
	11/29/1999	LER 1999-006-00:on 10/29/99,missed TS requirement for low power core physics test,was determined.Root cause analysis in progress.Low power core physics test procedure revised to reinsert prerequisite to perform control rod drop testing within 7 days.	ML993370580
	12/30/1999	LER 99-006-01 for the Fort Calhoun Station re missed technical specification requirement for low power core physics test.	ML003677071
	04/06/2000	Fort Calhoun Station, Recalculation of Dose to the Control Room Operators Places the Plant Outside Design Basis, LER	ML003702061
	05/26/2000	Fort Calhoun Station, Inoperability of Auxiliary Feedwater Pump Due to Speed Oscillations During Testing, LER	ML003719540
	07/28/2000	Fort Calhoun, Cancellation of LER-00-002-00	ML003737192
	12/01/2000	LER 00-002-00, Fort Calhoun Station, Plant Operation Outside of Low Temperature Overpressure Analysis Assumptions	ML003774332
	12/04/2000	LER 00-003-00, Fort Calhoun Station, Failure of Component Cooling Water System Valves by a Potential Common-Mode	ML003776352
	03/16/2001	LER 00-003-01 for Fort Calhoun Nuclear Station Unit Number 1 re Failure of Component Cooling Water System Valves by a Potential Common Mode.	ML010800047
	04/25/2001	LER 01-001-00 for Fort Calhoun Re primary safety valves outside lift setting acceptance range.	ML011200020
	01/16/2002	LER 02-001-00 for Fort Calhoun Nuclear Station Unit 1 re Contraband Found in a Vehicle During Entrance Search to the Site Protected Area.	ML020630643
	06/03/2002	LER 02-002-00 for Fort Calhoun, Unit 1 re Inappropriate Use of Manual Operator Action Renders Multiple Safety Systems Inoperable.	ML021640106
	10/04/2002	LER 02-S01-00 for Fort Calhoun Unit 1 Regarding Possible Error in Classification of Safeguards Material on September 6, 2002.	ML022900492
	12/20/2002	LER 02-003-00 for Fort Calhoun Unit 1 re Inadequate Cable Separation Resulting in Noncompliance with 10 CFR 50 Appendix R.	ML023650504
	02/13/2003	LER 02-004-00 for Fort Calhoun Unit 1 re Inadequate Procedural Guidance Resulting in Noncompliance with 10 CFR 50 Appendix R.	ML030520235
	05/05/2003	LER 03-001-00 for Fort Calhoun Unit 1 re Lack of Guidance Results in Noncompliance with Technical Specification Surveillance Requirement.	ML031340479
	08/28/2003	LER 03-002-00 for Fort Calhoun Unit 1 Regarding Inadequate Testing of Diesel Generators Due to Air Start Systems Unique Design.	ML032521409
	10/23/2003	LER 03-S01-00 for Fort Calhoun Station Regarding Safeguard System Vulnerability Due to Inadequate Securing of a Security Door.	ML033030498
	11/11/2003	LER 03-003-00 for Calhoun Station re Reactor Trip During Plant Shutdown.	ML033250339
	01/08/2004	LER 03-S02-00 for Fort Calhoun, Unit 1 regarding Lack of Proper Compensation for a Security Zone.	ML040150563
	09/24/2004	LER 04-001-00 for Fort Calhoun regarding Failure to Perform a Leakage Test Due to Lack of Understanding of Performance Design.	ML042680476

	10/14/2004	LER 04-S01-00 for the Fort Calhoun Station Regarding Inadequate Security Compensatory Measures for a Security Zone.	ML042890273
	12/17/2004	LER 04-002-00 Fort Calhoun Station Regarding Inoperable Diesel Generator for 28 Days Due to Blown Fuse During Shutdown.	ML050060085
	04/27/2005	LER 05-001-00 for Fort Calhoun Nuclear Station re Unplanned Reactor Trip Due to a Feedwater Transient at Low Power During Plant Shutdown.	ML051230141
	10/03/2005	LER 05-002-00 for Fort Calhoun Station Re: Inoperability of Pressurizer Power Operated Relief Block Valve Due to Human Error.	ML052850321
	06/07/2006	LER 06-001-00 for Fort Calhoun Station re Failure to Report Inoperable Containment Air Lock Valve Violates Technical Specifications.	ML061640265
	09/05/2006	LER 06-002-00 for Fort Calhoun Station, re Inadequate Design Control Results in Potentially Insufficient Auxiliary Feedwater Flow.	ML062560050
	11/06/2006	LER 06-003-00 for Fort Calhoun re Technical Specification Violation of Containment Air Coolers Due to Untimely Corrective Actions.	ML063190333
	11/10/2006	LER 06-004-00 for Fort Calhoun Station re Loss of Shutdown Cooling Redundant Train Due to Valve Mispositioning.	ML063250339
	12/11/2006	LER 06-005-00 For Fort Calhoun Station Regarding Faulty Maintenance Renders One Train of Containment Spray System Inoperable.	ML063530478
	01/08/2007	LER 06-006-00 For Fort Calhoun Regarding Inadvertent Start of Emergency Diesel Generator 2.	ML070170373
	01/08/2007	LER 06-007-00 for Fort Calhoun Regarding Inadequate Seismic Design of Reactor Vessel Head Refueling Stand.	ML070170381
	01/26/2007	LER 06-008-00 for Fort Calhoun Regarding Loss of Shutdown Cooling Due to Repressurizing Reactor Coolant System.	ML070370207
	03/29/2007	LER 07-001-00 for Fort Calhoun Re. Inoperability of a Post Accident Main Steam Line Radiation Monitor Due to Procedural Error.	ML071020167
	04/09/2007	LER 07-002-00 for Fort Calhoun regarding Common Mode Failure of Medium Voltage (4160) Circuit Breaker.	ML071070290
	04/17/2007	LER 07-003-00 for Calhoun Regarding Inoperability of a Diesel Generator with Inoperable Containment Spray Pump from the Opposite Bus.	ML071140029
	05/10/2007	Event Notification for Fort Calhoun on Offsite Notification Due to Elevated Tritium Levels.	ML101470606
	06/11/2007	LER 07-004-00 for Fort Calhoun Station re Inadvertent Isolation of All Containment Spray Due to an Inadequate Test Procedure.	ML071700086
	12/17/2007	LER 07-005-00 for Fort Calhoun Station re: Inadequate Operability Determination Results in Technical Specification Violation.	ML073580074
	04/30/2008	LER 06-002-01 for Fort Calhoun Station re: Inadequate Design Control Results in Potentially Insufficient Auxiliary Feedwater Flow.	ML081300430
	05/13/2008	LER 08-001-00 for Fort Calhoun Station re: Reactor Trip Due to Turbine Control System Failure.	ML081420025
	05/14/2008	LER 08-002-00 for Fort Calhoun Station re: Loss of Containment Integrity Due to a Leaking Isolation Valve.	ML081360080
	05/21/2008	LER 07-003-01 for Fort Calhoun Station re: Inoperability of a Diesel Generator with an Inoperable Containment Cooling Fan from the Opposite Bus.	ML081420716
	09/03/2008	LER 08-002-01 for Fort Calhoun re: Loss of Containment Integrity Due to a Leaking Isolation Valve.	ML082480453
	01/12/2009	LER 08-003-00 for Fort Calhoun Regarding Operation With Inoperable EDG and Opposite Train Feature Prohibited by TS.	ML090280367
	01/23/2009	LER 08-001-02 for Fort Calhoun Station re: Reactor Trip Due to Turbine Control System Failure.	ML090280584

	03/13/2009	LER 09-001-00 for Fort Calhoun Station re: Failure to Monitor Waste Gas Transfer Due to Operator Error.	ML090820084
	04/17/2009	LER 08-003-01 for Fort Calhoun Regarding Operation With Inoperable EDG and Opposite Train Feature Prohibited by TS.	ML091350051
	08/03/2009	LER 09-002-00 for Fort Calhoun Station re: Technical Specification Violation due to Installation of an Unqualified Part in a Radiation Monitor.	ML092230341
	08/10/2009	LER 09-003-00 for Fort Calhoun Regarding Void in Safety Injection Piping During Operation Due to Inadequate Procedural Guidance.	ML092300233
	02/02/2010	LER 09-004-00 for Fort Calhoun Station Regarding Containment Integrity was Unknowingly Violated During Performance of Leak Test.	ML100490163
	02/10/2010	LER 09-005-00 from Fort Calhoun Station Re: Inoperable Auxiliary Feedwater Train Due to an Inoperable Injection Valve.	ML100540116
	04/23/2010	LER 09-004-01 for Fort Calhoun Station, re: Containment Integrity Unknowingly Violated During Performance of a Leak Test.	ML101250148
	05/03/2010	LER 09-005-01 for Fort Calhoun Regarding Inoperable Auxiliary Feedwater Train Due to an Inoperable Injection Valve.	ML101340125
	06/04/2010	LER 10-002-00 for Fort Calhoun Regarding Failed Feeder Cable Due to Inadequate Procedure Causes Station Shutdown.	ML101610090
	06/04/2010	LER 10-001-00, for Fort Calhoun Station, Regarding Containment Integrity Violated During Performance of Leak Test.	ML101610091
	07/12/2010	Special Report on Inoperability of Main Steam Line Radiation Monitor RM-064 for Post Accident Monitoring.	ML101940066
	08/04/2010	Cancellation of Licensee Event Report 2009-003 for the Fort Calhoun Station.	ML102230421
	08/26/2010	LER 10-001-01 for Fort Calhoun Station Regarding Containment Integrity Violated During Refueling Leak Test Due to Inadequate Training.	ML102520373
	08/30/2010	LER 10-004-00, for Fort Calhoun Station, Regarding Acoustic Monitor Failure Due to Inadequate Barriers for Protection of Cable.	ML102430366
	10/08/2010	LER 10-005-00 for Fort Calhoun Regarding Inoperability of the Emergency Diesel Generator Fuel Oil Transfer System.	ML102810510
	01/19/2011	LER 10-005-01 for Fort Calhoun Station, regarding Inoperability of the Emergency Diesel Generator Fuel Oil Transfer System.	ML110840451
	02/22/2011	LER 10-006-00 for Fort Calhoun Regarding Reactor Trip Due to Erroneous Moisture Separator Trip Signal.	ML110540022
	03/28/2011	LER 11-001-00 for Fort Calhoun, Regarding Inadequate Flooding Protection Due To Ineffective Oversight.	ML110871994
	04/04/2011	LER 11-003-00, for Fort Calhoun Station, Regarding Inadequate Flooding Protection Due to Ineffective Oversight.	ML110950135
	04/04/2011	LER 11-002-00 for Fort Calhoun Station Regarding Failure of an RPS Trip Unit.	ML110950134
	04/05/2011	LER 11-004-00 for Fort Calhoun, Regarding Isolation of Both Trains of Safety Related Auxiliary Feedwater.	ML110960214
	04/29/2011	LER 10-006-01 for Fort Calhoun, Regarding Reactor Trip Due to Erroneous Moisture Separator Trip Signal.	ML111220074
	05/09/2011	LER 11-005-00 for Fort Calhoun Station Regarding Failure to Correctly Enter Technical Specifications Limiting Condition for Operation for the Reactor Protective System.	ML111300096
	05/16/2011	LER 11-003-01 for Fort Calhoun, Regarding Inadequate Flooding Protection Due to Ineffective Oversight.	ML111370123
	05/23/2011	LER 11-006-00, for Fort Calhoun Regarding Inoperability of Both Trains of Containment Coolers Due to a Mispositioned Valve.	ML111440216

	06/17/2011	LER 11-007-00 For Fort Calhoun Station Regarding Violation of Technical Specifications due to Reactor Coolant System Boundary Leakage.	ML111710274
	07/27/2011	LER 11-002-01 for Fort Calhoun Station Regarding Failure of an RPS Trip Unit.	ML112081990
	07/28/2011	LER 11-004-01 for Fort Calhoun Station, Regarding Isolation of Both Trains of Safety Related Auxiliary Feedwater.	ML112101477
	08/24/2011	LER 11-009-00 for Fort Calhoun Regarding Manual Start of a Safety System.	ML112360585
	10/27/2011	LER 11-008-01 for Fort Calhoun, Regarding Fire in Safety Related 480 Volt Electrical Bus.	ML113010208
	12/17/2011	LER 11-003-03 for Fort Calhoun Station Regarding Inadequate Flooding Protection Due To Ineffective Oversight.	ML113530555
	03/01/2012	LER 11-003-02 for Fort Calhoun, Regarding Inadequate Flooding Protection Due to Ineffective Oversight.	ML12061A224
	04/10/2012	LER 12-001-00 for Fort Calhoun Regarding Inadequate Flooding Protection Procedure.	ML12102A096
	04/23/2012	LER 12-005-00, for Fort Calhoun Station, Regarding TS Violation Due to Inadequate Testing of DG Fuel Pumps.	ML12115A172
	04/23/2012	LER 12-005-00 for Fort Calhoun Station Regarding TS Violation Due to Inadequate Testing of DG Fuel Pumps.	ML12250A189
	05/01/2012	LER 12-002-00 for Fort Calhoun Regarding Inadequate Qualifications for Containment Penetrations Renders Containment Inoperable.	ML12208A313
	05/11/2012	LER 12-003-00 for Fort Calhoun Station Regarding Non-Conservative Error in Calculation for Alternate Hot Leg Injection Results in Unanalyzed Condition.	ML12135A286
	05/11/2012	LER 12-003-00 for the Fort Calhoun Station Regarding Non-Conservative Error in Calculation for Alternate Hot Leg Injection Results in Unanalyzed Condition.	ML12135A379
	05/29/2012	LER 12-004-00 for Fort Calhoun Station re Inadequate Analysis of Drift Affects Safety Related Equipment.	ML12208A037
	06/01/2012	LER 12-005-01 for Fort Calhoun Station Regarding Technical Specification Violation Due to Inadequate Testing of Emergency Diesel Fuel Pumps.	ML12157A127
	06/25/2012	LER 12-006-00 for Fort Calhoun Regarding Operation of Component Cooling Pumps Outside of the Manufacturers Recommendation.	ML12178A293
	07/20/2012	LER 12-007-00 for Fort Calhoun Regarding Failure of Pressurizer Heater Sheath.	ML12205A188
	07/23/2012	LER 12-009-00 for Fort Calhoun Station, Regarding Inoperable Equipment due to Lack of Environmental Qualifications.	ML12206A056
	07/27/2012	LER 12-008-00 for Fort Calhoun Station Regarding Technical Specification Violation for Fuel Movement (VA-66).	ML12212A334
	08/03/2012	LER 12-010-00 for Fort Calhoun Station Regarding Seismic Qualification of Instrument Racks.	ML12219A010
	08/06/2012	LER 12-011-00 for Fort Calhoun Station, Regarding Emergency Diesel Inoperability Due to Bus Loads During a LOOP.	ML12220A167
	08/10/2012	LER 12-004-01 for Fort Calhoun Station, "Inadequate Analysis of Drift Affects Safety Related Equipment".	ML12226A179
	08/13/2012	LER 12-012-00 for Fort Calhoun, Regarding Multiple Safety Injection Tanks Rendered Inoperable.	ML12227A289
	08/17/2012	LER 12-013-00 for Fort Calhoun Station Regarding Inadequate Calculation of Uncertainty Results a Technical Specification Violation.	ML12233A178
	08/30/2012	LER 12-015-00 for the Fort Calhoun Station, "Electrical Impacted by High Energy Line Break Outside of Containment".	ML12244A053
	09/10/2012	LER 12-014-00 for Fort Calhoun Regarding Containment Beam 22 Loading Conditions Outside of the Allowable Limits.	ML12255A038

	09/17/2012	LER 12-016-00 for Fort Calhoun Station Regarding Unanalyzed Charging System Socket Welds to the Reactor Coolant System.	ML12262A317
	09/24/2012	LER 12-017-00 for Fort Calhoun Station Regarding Containment Valve Actuators Design Temperature Ratings Below those Required for Design Basis Accidents.	ML12268A237
	09/25/2012	LER 12-018-00 for the Fort Calhoun Station, "Containment Air Cooling Units Operated Outside of Technical Specifications during Cycle 26".	ML12270A134